



YOUR SEAT TRACKS ARE BEING **DAMAGED!**



Issue:



OEM Design:

- Damages seat track
- Reduces lifespan
- Frequent repairs

Pexco's APEX Solution:



Pexco Design:

- Patented wings
- Enhances stability
- Extends lifespan



Affected Part Numbers:

BAC1522-180, BAC1522-750

Applicable Models:

737, 777, 787

-100, 200, 200C, 300, 400, 500,
600, 700, 700C, 800, 900, 900ER, 8